

OTIF



**ORGANISATION INTERGOUVERNEMENTALE POUR
LES TRANSPORTS INTERNATIONAUX FERROVIAIRES**

**ZWISCHENSTAATLICHE ORGANISATION FÜR DEN
INTERNATIONALEN EISENBAHNVERKEHR**

**INTERGOVERNMENTAL ORGANISATION FOR INTER-
NATIONAL CARRIAGE BY RAIL**

OTIF/RID/CE/GTP/2012/8

26 September 2012

Original: English

RID: 1st Session of the RID Committee of Experts' standing working group
(Riga, 12 – 15 November 2012)

Subject: Report on a rail accident at Kijfhoek marshalling yard (near Zwijndrecht) on
14 January 2011

Transmitted by the Netherlands



Photo 1

For reasons of cost, only a limited number of copies of this document have been made. Delegates are asked to bring their own copies of documents to meetings. OTIF only has a small number of copies available.

1. Introduction

On the evening of Friday, 14 January 2011, a tank wagon with ethanol caught fire after a collision at the marshalling yard in Kijfhoek. No casualties were involved.



Photo 2

Kijfhoek track no.	Wagons and dangerous goods involved (see also photo 1)
132	covered wagons loaded with steel (1 wagon caught fire)
131	20 tank wagons loaded with UN 1170 ethanol (1 wagon caught fire), 2 tank wagons with UN 1131, 1 tank wagon empty uncleaned of UN 2447 and 1 wagon loaded with a tank-container empty uncleaned of UN 3394
130	Empty track
129	23 tank wagons, empty and cleaned of LPG

2. The accident in chronological order

a. The shunting process led to a collision

By means of hump shunting, 2 sets each composed of 4 wagons rolled to their destination track at too high a speed. As a consequence, a severe collision took place with wagons that were already on that track and between both sets of 4 wagons.

b. The collision led to wagon damage and fire

After the first collision one set of wagons rolled back. The damage picture and calculation demonstrated that the second collision was the most severe and occurred at an impact speed of around 24 km/h. During these collisions the frames of some wagons buckled. The buckle in the frame of one wagon was such that the tank leaked ethanol, which then caught fire. The frame of this wagon had one beam in the middle of the car. This beam serves to connect the two wagon ends (for longitudinal forces from the buffers) and to support the tank. Other tank-wagons in the train had two beams, one left and one right, in line with the buffers.

c. Fire-fighting

During the fire-fighting it appeared that the paperwork on the dangerous goods did not always correspond to the actual contents and location of the wagons in the marshalling yard. At first a risk of explosion was expected from two LPG tank-wagons that were situated on the second track (no.

129) next to the track (no. 131) with the burning ethanol wagon. At a later stage it appeared that these two wagons were empty and cleaned. Certain wagons with dangerous goods were also situated where they should not have been according to the paperwork.

3. Crash resistance of wagons

The Dutch Safety Board carried out an exploratory study on the crash resistance of wagons and mentioned the following:

The consequences (fire) of the accident seem to be relatively high at an impact speed of around 30 km/h.

With respect to crash resistance the buffers and frames of wagons are important. In a collision the buffers can only absorb part of the impact energy. Wagon frames must be sufficiently strong to transfer the remaining energy to the adjacent wagon.

Buffers

The buffers fitted should not be expected to absorb the entire impact¹. The impact was too strong. Part of the impact energy must be transformed into the deformation of the wagons, as happened in the accident.

In the burnt out wagon and some other wagons involved in the collision the buckle occurred on the same spot of the frame; the buckle was most severe in the burnt out ethanol wagon, which endured the highest impact (see photos 3-6).

Crash buffers

Nowadays more crash resistant buffers (so called crash buffers) are on the market, which can absorb more energy². These crash buffers are only obligatory for goods that are more dangerous than ethanol. Crash buffers could reduce the consequences of the accident, but the investigation has not demonstrated that with certainty.

4. Some lessons to be learned

- The information on marshalling yards with respect to the presence and location of dangerous goods wagons appeared not to be optimal in terms of giving the fire fighters the information needed for a quick and adequate emergency response. Further investigation by the Human Environment and Transport Inspectorate showed that the information flow should be improved at other marshalling yards as well. Arrangements to be made between the infrastructure manager and freight carriers to improve the information flow needed for a quick and adequate emergency response are still under discussion.
- The consequences (fire) of the collision were relatively severe. Improving the crash resistance of wagons should be considered. Crash buffers can limit the damage.

¹ The 4 buffers involved in the accident can absorb 50 kJ energy in total according to UIC leaflet 526-1, 1981 "Wagons – Buffers with a stroke of 105 mm", while each wagon possessed about 2000 kJ kinetic energy. The UIC leaflet prescribes impact tests to demonstrate the wagon strength and functioning of buffers. These tests are related to an impact speed of 12 km/h. In the accident the speed was more than twice as fast and as a consequence the energy to be absorbed was 4 times higher than the energy used for the construction of a wagon.

² Up to 400 kJ per buffer, so 1600 kJ per collision between two wagons.

Photos of burnt out tank wagon with buckled supporting beam



Photo 3



Photo 4



Photo5



Photo 6

1. Mode	
<input checked="" type="checkbox"/> Rail Wagon number (optional): 3387 7853 073-7	<input type="checkbox"/> Road Vehicle registration (optional):
2. Date and location of occurrence	
Year: 2011 Month: January Day: 14 Time: 21:35	
<input type="checkbox"/> Station <input checked="" type="checkbox"/> Shunting/marshalling yard <input type="checkbox"/> Loading/unloading/transshipment site Location / Country: Kijfhoek / Netherlands or <input type="checkbox"/> Open line Description of line: Kilometres:	Road <input type="checkbox"/> Built-up area <input type="checkbox"/> Loading/unloading/transshipment site <input type="checkbox"/> Open road Location / Country:
3. Topography	
<input type="checkbox"/> Gradient/incline <input type="checkbox"/> Tunnel <input type="checkbox"/> Bridge/Underpass <input type="checkbox"/> Crossing	
4. Particular weather conditions	
<input type="checkbox"/> Rain <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Fog <input type="checkbox"/> Thunderstorm <input type="checkbox"/> Storm Temperature: 7 °C	
5. Description of occurrence	
<input type="checkbox"/> Derailment/Leaving the road <input checked="" type="checkbox"/> Collision <input type="checkbox"/> Overturning/Rolling over <input type="checkbox"/> Fire <input type="checkbox"/> Explosion <input type="checkbox"/> Loss <input type="checkbox"/> Technical fault Additional description of occurrence: Collision and subsequent leaking of the shell and catching fire of the released product, during hump shunting of wagon 3387 7853 073-7 loaded with 58 738 kg ethanol (HIN 33/UN 1170)	

6. Dangerous goods involved						
UN Num-ber ⁽¹⁾	Class	Packing Group	Estimated quantity of loss of products (kg or l) ⁽²⁾	Means of containment ⁽³⁾	Means of containment material	Type of failure of means of containment ⁽⁴⁾
1170	3	II	58 738 kg	7	steel	1/2
(1) For dangerous goods assigned to collective entries to which special provision 274 applies, also the technical name shall be indicated.				(2) For Class 7, indicate values according to the criteria in 1.8.5.3.		
(3) Indicate the appropriate number 1 Packaging 2 IBC 3 Large packaging 4 Small container 5 Wagon 6 Vehicle 7 Tank-wagon 8 Tank-vehicle 9 Battery-wagon 10 Battery-vehicle 11 Wagon with demountable tanks 12 Demountable tank 13 Large container 14 Tank-container 15 MEGC 16 Portable tank				(4) Indicate the appropriate number 1 Loss 2 Fire 3 Explosion 4 Structural failure		
7. Cause of occurrence (if clearly known)						
<input type="checkbox"/> Technical fault <input type="checkbox"/> Faulty load securing <input checked="" type="checkbox"/> Operational cause (rail operation) <input type="checkbox"/> Other:						
8. Consequences of occurrence						
<u>Personal injury in connection with the dangerous goods involved:</u> <input type="checkbox"/> Deaths (number:) <input type="checkbox"/> Injured (number:) <u>Loss of product:</u> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Imminent risk of loss of product <u>Material/Environmental damage:</u> <input type="checkbox"/> Estimated level of damage ≤ 50,000 Euros <input checked="" type="checkbox"/> Estimated level of damage > 50,000 Euros <u>Involvement of authorities:</u> <input checked="" type="checkbox"/> Yes → <input checked="" type="checkbox"/> Evacuation of persons for a duration of at least three hours caused by the dangerous goods involved <input checked="" type="checkbox"/> Closure of public traffic routes for a duration of at least three hours caused by the dangerous goods involved <input type="checkbox"/> No						

If necessary, the competent authority may request further relevant information.