

# OTIF



**ORGANISATION INTERGOUVERNEMENTALE POUR  
LES TRANSPORTS INTERNATIONAUX FERROVIAIRES**

**ZWISCHENSTAATLICHE ORGANISATION FÜR DEN  
INTERNATIONALEN EISENBAHNVERKEHR**

**INTERGOVERNMENTAL ORGANISATION FOR INTER-  
NATIONAL CARRIAGE BY RAIL**

**INF.2**

11 April 2014

Original: German

**RID:** 3<sup>rd</sup> Session of the RID Committee of Experts' standing working group  
(Berne, 20 and 21 May 2014)

**Subject:** Report on incidents in the carriage of dangerous goods in accordance with RID  
1.8.5 (Hamburg-Billwerder, 3 July 2013)

### Information from Germany

1. On 3 July 2013, an incident occurred in Hamburg-Billwerder when a tank-container was being transshipped (by crane) from a road vehicle onto a carrying wagon. The crane operator failed to set the tank-container directly onto the attachment pins on the carrying wagon, and when turning, touched the supporting frame on the carrying wagon. The tank-container's fittings cabinet was bent upwards and the load leaked. See also the attached report on incidents in the carriage of dangerous goods in accordance with RID 1.8.5 (Annex 1) and an extract from a report by the German Federal Office of Railways (Eisenbahn-Bundesamt) dated 4 July 2013 (Annex 2).
2. The container carrying wagon was a so-called "pocket wagon" (design type 743). This wagon design type is also used especially for loading trailers. It has a supporting frame for the trailer's kingpin.
3. However, this construction seems to cause problems when loading tank-containers. In this case, once the tank-container had been placed on the carrying wagon, there was only 20 cm gap between the tank and the support frame.
4. If you consider the view the crane operator has and the movement of the tank-container on the crane's suspension cables (caused by movement of the crane or wind or surging movements), repetition of such an incident cannot be ruled out.

For reasons of cost, only a limited number of copies of this document have been made. Delegates are asked to bring their own copies of documents to meetings. OTIF only has a small number of copies available.

5. In terms of further investigations, the question arises

- as to whether internal operating instructions issued by individual private transshipment facilities are sufficient to prevent such incidents in future?

*(Note: These instructions say that when loading onto pocket wagons of design type 743, tank-containers must be loaded on such that the fittings are toward the middle of the wagon.)*

- or whether, for loading tank-containers onto these particular container carrying wagons, separate handling provisions should also be prescribed in Part 7 of RID?

6. Germany would be pleased to hear the opinion of other States on this so that the next steps could be agreed.

---

Annex 1

<b>1. Mode</b>	
<input checked="" type="checkbox"/> Rail Wagon number (optional): <b>3180 451 2082-7</b> .....	<input type="checkbox"/> Road Vehicle registration (optional): .....
<b>2. Date and location of occurrence</b>	
Year: <b>2013</b> ..... Month: <b>July</b> ..... Day: <b>03</b> ..... Time: <b>19.40</b> .....	
<input type="checkbox"/> Station <input type="checkbox"/> Shunting/marshalling yard <input checked="" type="checkbox"/> Loading/unloading/transshipment site Location / Country: ..... or <input type="checkbox"/> Open line Description of line: ..... Kilometres: .....	Road <input type="checkbox"/> Built-up area <input type="checkbox"/> Loading/unloading/transshipment site <input type="checkbox"/> Open road Location / Country: .....
<b>3. Topography</b>	
<input type="checkbox"/> Gradient/incline <input type="checkbox"/> Tunnel <input type="checkbox"/> Bridge/Underpass <input type="checkbox"/> Crossing	
<b>4. Particular weather conditions</b>	
<input type="checkbox"/> Rain <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Fog <input type="checkbox"/> Thunderstorm <input type="checkbox"/> Storm Temperature: ... °C	
<b>5. Description of occurrence</b>	
<input type="checkbox"/> Derailment/Leaving the road <input type="checkbox"/> Collision <input type="checkbox"/> Overturning/Rolling over <input type="checkbox"/> Fire <input type="checkbox"/> Explosion <input checked="" type="checkbox"/> Loss <input type="checkbox"/> Technical fault  Additional description of occurrence:  <b>Damage caused by crane transshipment</b> ..... ..... ..... ..... ..... ..... ..... ..... .....	



**Extract from the Eisenbahn-Bundesamt (EBA) report  
(Hamburg/Schwerin branch) dated 4 July 2013**

On 4 July 2013, the Hamburg-Billwerder transshipment station informed EBA of a leaking tank-container (incident: 3 July 2013 at about 7.40 pm). Around 2,400 litres of hexanol had leaked and the Hamburg fire brigade had responded with a large number of emergency response teams.

Photograph 1: Incident site during the emergency response



When EBA staff arrived at the incident site at about 10.00 on 4 July 2013, initial enquiries revealed the following:

1. On 3 July 2013, tank-container ANHU 235 159 – 0, loaded with 25,800 kg 30 UN 2282 HEXANOL, 3, III, was to be transhipped from a road vehicle onto a carrying wagon.
2. The crane operator failed to set the tank-container directly onto the attachment pins, and when turning, touched the supporting frame on the carrying wagon. The fittings cabinet was bent upwards and the load leaked.
3. The fire brigade was unable to take effective measures to seal off the leak on the carrying wagon.
4. A replacement tank-container was requested and the load was pumped into this replacement.
5. A trailer was used to bring the damaged tank-container onto a drip collection device.

Photograph 2: Tank-container in the drip collector next day



Photograph 3: Close-up of the fittings cabinet bent upwards



Photograph 4: Damaged weld seam



As no further measures could be taken in situ, the empty, uncleaned tank-container was taken to the workshop (by lorry) to be repaired.

The water police (competent authority) was notified and the transport operation took place in accordance with ADR 1.4.2.2.4.

The competent authority in Hamburg responsible for ensuring compliance with the CSC Convention was also notified and is supervising the repair work.

The damaged parts were removed in the workshop. The buckling on the valve attachment plate was clearly visible.

Photograph 5: Valve unit (attachment plate is buckled)



In order to clarify the question of whether it was simply human error or problems with the loading method that caused the incident, on 4 September 2013, EBA staff had a meeting at Billwerder with the people involved. An operator provided a tank-container of the same construction, on which the tank itself protruded over the container frame **on both sides** (so-called swap tank-container).

Photograph 6: Tank-container of same construction



The tank-container was loaded onto a container carrying wagon, which was also the same construction as the one involved in the incident. This wagon design type is also used for loading trailers (so-called pocket wagon).

Photograph 7: Illustrative photograph – Loading a trailer onto a pocket wagon



Photograph 8: Pocket wagon of same construction



Photograph 9: At the front, an attachment pin for receiving the load unit can be seen and in the background, the supporting frame for receiving the kingpin of the trailer.



Photograph 10: Crane operator's view of the loading operation



After the tank-container has been placed onto the carrying wagon, it can be seen that there is only a 20 cm gap between the tank and the supporting frame.

Photograph 11: Close-up view – Distance between tank-container/support frame – here: 20 cm



If you consider the view the crane operator has and the movement of the tank-container on the crane's suspension cables (caused by movement of the crane or wind or surging movements), repetition cannot be ruled out.

All those involved agreed that appropriate precautions must be taken here to prevent a repetition of this incident.

Those involved informed EBA that there was already a set of operating instructions for this: All tank-containers (i.e. not just the so-called swap tank-containers) should, without exception, be loaded onto pocket wagons (design type 743) in such a way that the fittings are toward the middle of the wagon. All crane operators were notified of this rule in an official training session and they confirmed this with their signature. In addition, the other terminals belonging to this operator were informed of the incident and the rule that had been decided.

Whether further-reaching precautions might have to be taken will depend on the success of the measure taken.

---