



OTIF/RID/CE/GTP/2017/14

6 octobre 2017

Original : allemand

RID : **8<sup>e</sup> session du groupe de travail permanent de la Commission d'experts du RID**  
(Utrecht, 20-24 novembre 2017)

Objet : **Maintien en service des wagons-citernes destinés au transport de gaz de la classe 2 selon les dispositions transitoires des paragraphes 1.6.3.3.2 à 1.6.3.3.5 du RID**

## Proposition de l'Autriche

### Introduction

1. Les dispositions transitoires sur le maintien en service des wagons-citernes destinés au transport de gaz de la classe 2 entrées en vigueur le 1<sup>er</sup> janvier 2015 autorisent :
  - l'utilisation des wagons-citernes construits entre le 1<sup>er</sup> janvier 1965 et le 31 décembre 1966 jusqu'au 31 décembre 2019 (**1.6.3.3.2**),
  - l'utilisation des wagons-citernes construits entre le 1<sup>er</sup> janvier 1967 et le 31 décembre 1970 jusqu'au 31 décembre 2021 (**1.6.3.3.3**),
  - l'utilisation des wagons-citernes construits entre le 1<sup>er</sup> janvier 1971 et le 31 décembre 1975 jusqu'au 31 décembre 2025 (**1.6.3.3.4**),
  - l'utilisation des wagons-citernes construits entre le 1<sup>er</sup> janvier 1976 et le 30 septembre 1978 jusqu'au 31 décembre 2029 (**1.6.3.3.5**).
2. La proposition de l'Allemagne à la 13<sup>e</sup> réunion du groupe de travail « Technique des citernes et des véhicules » (OTIF/RID/CE/GT/2012/3) et le document de consultation (INF.10) de la 1<sup>re</sup> session du groupe de travail permanent de la Commission d'experts du RID détaillaient les différences d'épaisseur minimale de paroi et les différences de qualité des matériaux et de leur utilisation et proposaient une comparaison approfondie des niveaux de sécurité. La condition essentielle à l'application de toutes ces dispositions transitoires est que les wagons-citernes satisfassent aux prescriptions du chapitre 6.8 en ce qui concerne les équipements.

### Situation actuelle

3. Depuis l'entrée en vigueur des dispositions transitoires, de nombreux contrôles ponctuels de tels wagons-citernes pour gaz ont été réalisés en Autriche. En 2015 et 2016, plus de 10 % des

wagons-citernes pour gaz contrôlés présentaient des défauts.

4. De manière générale, le constat était que sur les « vieux » wagons-citernes, les équipements répondaient certes en théorie aux prescriptions du chapitre 6.8, mais que la plupart ne fonctionnaient pas.
5. Principaux défauts constatés :
  - recours à des clapets de fond complètement obsolètes (principalement mécaniques) qui ne sont plus utilisés dans les wagons-citernes récents,
  - équipements de service difficiles à manipuler,
  - modes d'emploi ne correspondant pas aux équipements en présence,
  - clapets de fond ouverts,
  - robinets pas complètement fermés en raison de défauts techniques,
  - robinets ouverts car la vis de pression d'urgence est vissée,
  - équipements et clapets de fond ouverts fixés avec des pierres, des cales en bois ou encore du fil métallique,
  - tiges des clapets de fond cassées,
  - mauvaises inscriptions sur les robinets ou manettes mal montées,
  - absence de certains équipements,
  - position ouverte ou fermée des robinets non indiquée.
6. En cas de déraillement, ces défauts faciliteraient la fuite de matières et pourraient entraîner des conséquences comme à Viareggio et Hitrino.
7. De plus, ces défauts constituent clairement des cas de non-conformité, lesquels ne devraient pas pouvoir se produire quand les obligations de sécurité des intervenants (en particulier du remplisseur, de l'exploitant et de l'ECE) définies au chapitre 1.4 du RID sont respectées. La pratique montre toutefois qu'ils sont relativement fréquents. L'âge des robinets et soupapes est à cet égard doublement problématique : outre la multiplication des défauts techniques, le personnel des intervenants concernés ne dispose plus des connaissances nécessaires sur leur fonctionnement. La situation devrait aller en s'aggravant dans les années à venir. Les autorités et gestionnaires d'infrastructure ne sont pas en mesure de réaliser des contrôles à 100 % garantissant le respect constant des prescriptions.

### Cause et conclusion

8. Une analyse des risques menée par ÖBB-Infrastruktur (voir annexe, en allemand et en anglais uniquement) montre que les wagons-citernes construits après 1978 sont 60 fois plus sûrs, c'est-à-dire qu'il y a 60 fois moins de chances que des incidents graves se produisent. Les contrôles actuellement effectués révèlent également que les citernes plus anciennes ne répondent pas aux règles de sécurité actuelles et que les risques potentiels sont donc élevés.
9. Ces éléments plaideraient en faveur d'une mise hors service immédiate de ces wagons. L'Autriche a toutefois conscience qu'avec les dispositions transitoires actuelles, il n'y a pas de méfiance envers leur maintien en service, malgré les mauvaises expériences vécues depuis et alors même que la situation devrait s'aggraver.

### Proposition

10. L'Autriche propose que les délais des dispositions transitoires des 1.6.3.3.4 et 1.6.3.3.5 soient fixés à 2021, comme pour le 1.6.3.3.3.
-

# Risk Assessment Report

## **Assessment of risk mitigation by means of the timely withdrawal of RID gas tank-wagons that do not meet the provisions of 1978**

**Date:** 09.05.2017

**Author:** Robert Weber,  
Manfred Dwornikowitsch  
**Proposer:** Peter Kleinschuster

**Experts:** Herbert Plöderl RCA; Gerhard Mayer RCA; Doris Frühauf RCA; Günter Kettler RCA; Alfred Körner Infrastruktur AG ;

**Distributors:** as above

## Background

For the carriage of highly sensitive goods (chlorine, carbon disulphide, hydrocarbon gases), tank-wagons are used whose characteristics (prerequisite for carriage) are governed by RID. On the basis of transitional periods, "old" tank-wagons are also used, whose technical standard no longer corresponds to current requirements.

However, gas tank-wagons that do not meet the provisions in force since 1 October 1978 may still be used on the basis of the transitional provisions in RID, sometimes up to 2029.

Note:

In Austria, carbon disulphide is now carried exclusively in new (mostly Wascosa) tank-wagons with the appropriate equipment, and is not therefore considered further in this analysis.

In the version of RID in force at the time of this RAR, there are transitional provisions for the continued use of older gas tank-wagons that were last amended on 1.1.2015. Based on the growing number of incidents, the transitional periods in the paragraphs in red would appear to be too long. In these cases, the period should be shortened.

### 1.6.3.3

Tank-wagons whose shells were built before the entry into force of the requirements applicable as from 1 October 1978 may still be used if their wall thickness and items of equipment meet the requirements of Chapter 6.8. = Indefinitely

#### 1.6.3.3.1

Tank-wagons which are intended for the carriage of gases of Class 2 and whose shells were built before the entry into force of the requirements applicable from 1 January 1965 may still be used until 31 December 2017 if their items of equipment but not their wall thickness meet the requirements of Chapter 6.8.

#### 1.6.3.3.2

Tank-wagons which are intended for the carriage of gases of Class 2 and whose shells were built between 1 January 1965 and 31 December 1966 may still be used until 31 December 2019 if their items of equipment but not their wall thickness meet the requirements of Chapter 6.8.

#### 1.6.3.3.3

Tank-wagons which are intended for the carriage of gases of Class 2 and whose shells were built between 1 January 1967 and 31 December 1970 may still be used until **31 December 2021** if their items of equipment but not their wall thickness meet the requirements of Chapter 6.8.

#### 1.6.3.3.4

Tank-wagons which are intended for the carriage of gases of Class 2 and whose shells were built between 1 January 1971 and 31 December 1975 may still be used until **31 December 2025** if their items of equipment but not their wall thickness meet the requirements of Chapter 6.8.

#### 1.6.3.3.5

Tank-wagons which are intended for the carriage of gases of Class 2 and whose shells were built between 1 January 1976 and 30 September 1978 may still be used until **31 December 2029** if their items of equipment but not their wall thickness meet the requirements of Chapter 6.8.

**Subject:****Aim:**

Gas tank-wagons built after the rules in force since 1.10.1978 are characterised by the greater wall strength of the metal sheets and a different type/quality of steel. In addition, the construction of the bottom valve has generally been improved. These measures reduce the risk of the load leaking in the event of a serious incident as a result of the significantly improved ductility. The material strength and type/quality of the steel appreciably help avoid the risk of the tank wall rupturing and the penetration of objects.

The aim of this risk analysis is to show the risk reduction mathematically.

**Intention:**

Tank-wagons not built at least in accordance with the provisions of RID applicable from

1.10.1978 should be replaced in the next 1-2 years and no longer used.

An immediate measure that is planned is to prohibit these wagons from being operated.

**Regulations:**

Currently applicable version of RID.

## Assumptions:

The calculation is made in the form of a semi-quantitative approach. The experts involved make certain assumptions.

The basis for the calculation is the average number of all incidents

- Train – collision
- Train – derailment

in the last 11 years.

## Calculation:

- On average each year, 1/5 of trains are freight trains.
- 11% of freight trains on the network have at least one RID wagon in the train.
- The number of relevant incidents is an average of those in years 2006 to 2016 taken from the statistics (unit BL – Safety) on derailments and collisions.  
Derailment and collisions were considered relevant because in such events, the load may leak as a result of the technical devices failing.
- The values assumed in the columns are estimates made by the experts based on:
  - the condition of the bottom valves after incidents and in checks
  - awareness (because of their activities) of incidents and the causes thereof.

**Number of freight trains per hour with an RID wagon =**  
 $((\text{total number of trains}/5)/100)*11)/(24h*365 \text{ hours of operation})$

Calculation according to “hours of operation” in order to reach values that are comparable to our safety targets.

### Factor =

Number of incidents (average)/number of freight trains per hour with an RID wagon

## Differences between pre- and post-1978 wagons:

- Tougher steel (ductility) and hence greater resistance to penetration by objects.
- Wall thickness (strength). It is not possible to make a general statement about the degree of strength as it depends on the medium to be carried (standardised calculation rules).
- More reliable bottom valves with clear operating and maintenance instructions.

## Consideration of the risk potential

This risk analysis was split into 2 “risk potentials”, as follows: Risk potential 1 shows the findings from inspections obtained as a result of the technical differences between the wagons. Risk potential 2 is a semi-quantitative calculation. It is semi-quantitative because the likelihoods were estimated by the experts. The statistics do not differentiate between wagons before and after 1978, so it was not possible here to calculate or ascertain any values.

### Risk potential 1 Leakage of dangerous goods with no preceding incident (derailment/collision)

#### **Reason:**

- .) The bottom valve design type in question may remain in the open position as a result of incorrect operation of the emergency forcing screw.
- .) This results in the load coming into contact with the side valves and blank flange covers. In this case, the unprotected pipes contain dangerous goods which continue to flow until the tank is emptied.
- .) Maintenance: Owing to the age of these wagons, there are maintenance difficulties with regard to:
  - replacement parts (sometimes no longer available)
  - knowledge of the technical characteristics of these wagons
- .) As it is planned to withdraw these wagons by 2029 at the latest (see Background), it can be assumed that they are no longer state of the art.

#### **Inspection data:**

In 2015 and 2016 (as at May 2017) (source RCA)

- **640** gas tank-wagons were inspected, of which
- **76** wagons had at least one of the defects listed above.

For the reasons listed above, it can therefore be deduced that there is potentially a high risk of dangerous goods leaking.

### Risk potential 2 Leakage of dangerous goods after an incident (derailment/collision):

This risk potential is calculated with an event tree. The values entered and used here were defined in coordination with the experts at the meeting.

The basis of calculation is the factor calculated in accordance with the formulae described in the paragraph on “assumptions”.

The calculation is shown on the following page as an event tree.

**Semi-quantitative Hazard Assessment:**

	Wagon event concerned (derailment/collision)	Piping behind bottom valves is wrenched off	Bottom valve leaks/is open	Tank wall penetrated		Result
				YES before 1978 0.02 YES after 1978 0.01		4.51E-11 7.52E-13
			YES before 1978 0.3 YES after 1978 0.01	NO before 1978 0.98 NO after 1978 0.99		5.16E-09 7.45E-11
				YES before 1978 0.02 YES after 1978 0.01		1.05E-10 7.45E-11
			NO before 1978 0.7 NO after 1978 0.99	NO before 1978 0.98 NO after 1978 0.99		No leakage No leakage
Factor 4.17806E-08	YES 0.2			YES before 1978 0.02 YES after 1978 0.01		1.17E-11
	NO 0.1		NO before 1978 0.7 NO after 1978 0.99	NO before 1978 0.98 NO after 1978 0.99		No leakage No leakage
	No	0.8 Not considered further, as the experts estimate the likelihood of leakage without derailment/collision beforehand to be less than the calculated likelihood.				
	The possibility of the piping NOT being wrenched off and the bottom valve not being open/leaking was also not calculated, as this would not lead to any leakage.					

	2006-2016		Derailment	Collision	
Average no. derailments	12.27272727		2006 16	2006 4	
Average no. collisions	4.636363636		2007 17	2007 5	
Total trains/year	2100000		2008 15	2008 4	
Factor	4.17806E-08		2009 12	2009 8	
Potential for derailment/collision per freight train with RID tank-wagons per hour of operation					
			2010 14	2010 6	
			2011 8	2011 5	
			2012 14	2012 3	
			2013 13	2013 6	
			2014 5	2014 2	
			2015 9	2015 5	
			2016 12	2016 3	
			12.2727273	4.63636364	

**Safety requirements/result:**

In order to reinforce the validity of this document, 2 risk potentials were considered.

**Risk potential 1:** Here, the statistical values of the checks on relevant gas tank-wagons carried out by ÖBB Infrastruktur are reflected. If the piping necessary for unloading that is situated behind the bottom valve were wrenched off, it is very likely that wagons built before 1978 would leak. This could occur as a result of a collision with objects or if a vehicle travels over a railway crossing without authorisation.

**Risk potential 2:** Here, the likelihood is calculated of dangerous goods leaking from wagons built before 1978 in comparison to wagons built after 1978 following a collision/derailment.

The result shows that for wagons built before 1978, in the worst case scenario (bottom valves leaking/open and tank wall penetrated), the likelihood is greater by 2 powers of ten.

Likelihood for wagons before 1978 : **4.51E-11**

Likelihood for wagons after 1978 : **7.52E-13**

Consequently, the likelihood of dangerous goods leaking from gas tank-wagons that do not meet the provisions applicable after 1978 is 60 (451/7.52) times greater than for wagons of a newer design type.

In summary, the experts, supported by the results of this RAR, recommend that the deadline for withdrawing wagons built before 1978, which is 13 years from the date of this RAR, should be reduced to the end of 2018. Another reason for this recommendation is the enormous extent of the damage that would occur if these chemicals were to leak.

It is also recommended that OTIF's report of the 13<sup>th</sup> session of the working group on tank and vehicle technology held in Rome on 11 and 12 April 2012 be taken into account.

**Limiting factors:**

None

**Akzeptanz:**

Das angewandte Verfahren und Methodik wird von allen der Sicherheitsanforderungen betroffenen Parteien akzeptiert.

**Erklärung:**

Der Risikomanager der ÖBB Infrastruktur AG ist für die Richtigkeit der Methodik, der dazugehörigen Prozesse, des Ablaufs der Analyse und gemäß seiner Fachkenntnisse und Erfahrung mitverantwortlich für die Qualität der Inhalte.

Die Inhalte und die Ergebnisse basieren auf den Sachkenntnissen der beteiligten ÖBB Mitarbeiter. Alle Entscheidungen und Annahmen werden übereinstimmend getroffen, Ausnahmen werden gesondert angeführt. Diese Entscheidungen und Annahmen basieren auf den, zu diesem Zeitpunkt, gültigen und verfügbaren Informationen.

Der Vorschlagende bestätigt, dass alle ermittelten Gefährdungen und die damit verbundenen Risiken auf einem vertretbaren Niveau gehalten werden.

Risikomanager

(Robert Weber)

Anfordernde der Risikoanalyse

(Peter Kleinschuster)

## Annex - Data collection

### Collection of data RAR risk liquefied gas wagons from RCA Annual Report 2015/2016

#### **2015:**

289,585 dangerous goods wagon movements, of which 23,628 gas tank-wagons for Class 2 = **7.9%**

4431 dangerous goods inspections carried out/7.9% of which is ~ 350 liquefied gas tank-wagons

As liquefied gas tank-wagons in Austria tend to be carried in groups of wagons, rather than as individual wagons, and as the loading points are few and far between, it is more difficult for RCA GGBA to check them. The calculated percentage of 350 RID gas wagon checks is therefore reduced by 20% → ~ **280 liquefied gas tank-wagons inspections/2015**

#### **2016:**

301,391 dangerous goods wagon movements, of which 24,871 gas tank-wagons for Class 2 = **8.2%**

4412 dangerous goods inspections carried out/8.2% of which is ~ **360 liquefied gas tank-wagon inspections 2016**

Owing to the increasing number of defects on liquefied gas wagons, in 2016 RCA BL ordered that special checks be carried out. These were carried out on a particular proportion of train-load consignments. Therefore, for 2016 there is no need to reduce the number of Class 2 tank-wagons by 20%.

### Summary of technical defects on liquefied gas wagons in 2015 and 2016

#### **2015:**

The 2015 summary documents 40 cases. The summary contains around 80% of all the technical defects on liquefied gas wagons in RCA trains in 2015.

Of these 40, 23 meet the criteria of the RAR→ aggregated over 100% this results in **28 tank-wagons** in 2015 that have been included in the analysis.

280 checks/28 relevant criticised points→ 10%

#### **2016:**

The 2016 summary documents 79 cases. The summary contains around 85% of all the technical defects on liquefied gas wagons in RCA trains in 2016.

Of these 79, 41 meet the criteria of the RAR→ aggregated over 100% this results in **48 tank-wagons** in 2015 that have been included in the analysis.

360 checks/48 relevant criticised points→ 13.3%

(In fact this percentage should be higher, because in the special checks in 2016, particularly problematic train-load consignments were checked. However, it should be noted that both keepers and wagon lessors reacted quickly and no longer used certain tank-wagons or used routes that did not go through Austria.)